

USS JOHN S. MCCAIN collision with MT ALNIC MC:


Insufficient Training, Inadequate Operating Procedures, Lack of Operational Oversight

Alan M. Weigel September 20, 2019

The information contained herein is abridged and summarized from numerous sources, the accuracy and completeness of which cannot be assured. This should not be construed as legal advice or opinion and is not a substitute for the advice of counsel.

The Singapore Straits TSS: One of the world's busiest








D 2018 BLANK ROME LLP. ALL RIGHTS RESERVED. PLEASE CONTACT BLANK ROME FOR PERMISSION TO REUSE.

Collision Location



BLANKROME

USS JOHN S. MCCAIN (DDG 56)



BLANKROME

ID 2018 BLANK ROME LLP, ALL RIGHTS RESERVED, PLEASE CONTACT BLANK ROME FOR PERMISSION TO REUSE.

MT ALNIC MC








2018 BLANK ROME LLP. ALL RIGHTS RESERVED. PLEASE CONTACT BLANK ROME FOR PERMISSION TO REUSE.

Size Comparison



ALNIC MC



© 2018 BLANK ROME LLP. ALL RIGHTS RESERVED. PLEASE CONTACT BLANK ROME FOR PERMISSION TO REUSE.





Find the full text of this and thousands of other resources from leading experts in dozens of legal practice areas in the <u>UT Law CLE eLibrary (utcle.org/elibrary)</u>

Title search: USS John S. McCain Collision with MT ALNIC MC: Insufficient Training, Inadequate Operating Procedures, Lack of Operational Oversight

Also available as part of the eCourse

Naval Collisions: The Importance of Training and Looking Out the Window

First appeared as part of the conference materials for the 28^{th} Annual David W. Robertson Admiralty and Maritime Law Conference session "Naval Collisions: The Importance of Training and Looking Out the Window"