

## USS JOHN S. MCCAIN collision with MT ALNIC MC:



Insufficient Training, Inadequate Operating  
Procedures, Lack of Operational Oversight

Alan M. Weigel  
September 20, 2019

*The information contained herein is abridged and summarized from numerous sources, the accuracy and completeness of which cannot be assured. This should not be construed as legal advice or opinion and is not a substitute for the advice of counsel.*


© 2018 BLANK ROME LLP. ALL RIGHTS RESERVED. PLEASE CONTACT BLANK ROME FOR PERMISSION TO REUSE.

## The Singapore Straits TSS: One of the world's busiest



© 2018 BLANK ROME LLP. ALL RIGHTS RESERVED. PLEASE CONTACT BLANK ROME FOR PERMISSION TO REUSE.

# Collision Location



# USS JOHN S. MCCAIN (DDG 56)




# MT ALNIC MC



## Size Comparison

MCCAIN



ALNIC MC

Find the full text of this and thousands of other resources from leading experts in dozens of legal practice areas in the [UT Law CLE eLibrary \(utcle.org/elibrary\)](https://utcle.org/elibrary)

Title search: USS John S. McCain Collision with MT ALNIC MC:  
Insufficient Training, Inadequate Operating Procedures, Lack of  
Operational Oversight

Also available as part of the eCourse

[2019 David W. Robertson Admiralty and Maritime Law eConference](#)

First appeared as part of the conference materials for the  
28<sup>th</sup> Annual David W. Robertson Admiralty and Maritime Law Conference session  
"Naval Collisions: The Importance of Training and Looking Out the Window"