



USS JOHN S. MCCAIN collision with MT ALNIC MC:

**Insufficient Training, Inadequate Operating
Procedures, Lack of Operational Oversight**


Alan M. Weigel
September 20, 2019

The information contained herein is abridged and summarized from numerous sources, the accuracy and completeness of which cannot be assured. This should not be construed as legal advice or opinion and is not a substitute for the advice of counsel.

The Singapore Straits TSS: One of the world's busiest



Collision Location



USS JOHN S. MCCAIN (DDG 56)




MT ALNIC MC



Size Comparison

MCCAIN



ALNIC MC

Find the full text of this and thousands of other resources from leading experts in dozens of legal practice areas in the [UT Law CLE eLibrary \(utcle.org/elibrary\)](https://utcle.org/elibrary)

Title search: USS John S. McCain Collision with MT ALNIC MC:
Insufficient Training, Inadequate Operating Procedures, Lack of
Operational Oversight

Also available as part of the eCourse

[2019 David W. Robertson Admiralty and Maritime Law eConference](#)

First appeared as part of the conference materials for the
28th Annual David W. Robertson Admiralty and Maritime Law Conference session
"Naval Collisions: The Importance of Training and Looking Out the Window"